



ELEMENTS PROPERTY REPORT



5915 Highland Hills Circle Fort Collins, CO, 80528, US

Vexcel Group

Report date: 05 February 2024








Property Attributes

IMAGE & ANALYSIS DATE: 17 July 2023




Pool	No	Hardscapes - Area	333 m²
Pool: In Ground Area	N/A	Hardscapes – Parcel area %	8%
Pool: Above Ground Area	N/A	Playground	No
Hot Tub - Area	N/A	Trampoline	No
Enclosure	No	Sports court	No
Diving Board	No	Vehicles: Automobile(s)	0
Water Slide	No	Vehicles: Boat(s)	0
Deck	Yes		





Primary Building: Attributes

IMAGE & ANALYSIS DATE: 17 July 2023




Ground elevation	1506.32 m	Chimney(s)	0
Footprint area	317.35 m ²	AC unit(s)	0
Roof elevation	1512.2 m	Roof vent(s)	14
Roof height	6.75 m	Satellite dish(es)	1
Roof centroid	-104.966454 40.471402	Skylight(s)	0
Tree cover over roof	0		
Roof solar	No		





Primary Building: Roof Attributes

IMAGE & ANALYSIS DATE: 17 July 2023




Roof shape	gable	Missing roof material	0%
Roof material	shingle	Roof tarp	0%
Roof condition	5/5	Debris	0%
Roof discoloration	0.03%		
Vent staining	0%		
Algae staining	0.03%		
Water pooling	0%		





Primary Building: Defensible Space

IMAGE & ANALYSIS DATE: 17 July 2023



DEFENSIBLE SPACE

DSB 5 ft	0%	DST 5 ft	1%
DSB 30 ft	0%	DST 30 ft	12%
DSB 100 ft	2%	DST 100 ft	15%
DSB 200 ft	4%	DST 200 ft	14%

DSB - Defensible space building

DST - Defensible space trees

Metrics above relate to 5, 30, 100, and 200 foot buffers for both buildings and trees.

Ex: 24% of the 100 ft buffer contains other buildings





Additional Building: Attributes

IMAGE & ANALYSIS DATE: 17 July 2023



Ground elevation	1506.93 m	Chimney(s)	0
Footprint area	82.31 m ²	AC unit(s)	0
Roof elevation	1509.58 m	Roof vent(s)	4
Roof height	3.79 m	Satellite dish(es)	0
Roof centroid	-104.966726 40.471368	Skylight(s)	0
Tree cover over roof	0		
Roof solar	No		





Additional Building: Roof Attributes

IMAGE & ANALYSIS DATE: 17 July 2023




Roof shape	gable	Missing roof material	0%
Roof material	shingle	Roof tarp	0%
Roof condition	5/5	Debris	0%
Roof discoloration	0%		
Vent staining	0%		
Algae staining	0%		
Water pooling	0%		





Additional Building: Defensible Space

IMAGE & ANALYSIS DATE: 17 July 2023



DEFENSIBLE SPACE

DSB 5 ft	0%	DST 5 ft	6%
DSB 30 ft	1%	DST 30 ft	23%
DSB 100 ft	8%	DST 100 ft	17%
DSB 200 ft	5%	DST 200 ft	15%

DSB - Defensible space building


DST - Defensible space trees

Metrics above relate to 5, 30, 100, and 200 foot buffers for both buildings and trees.

Ex: 24% of the 100 ft buffer contains other buildings




COLLECTION TYPE: URBAN (MOST RECENT URBAN ORTHO IMAGES)



URBAN - NEIGHBORHOOD OVERVIEW


IMAGE DATE: 17 July 2023



URBAN - ORTHO



COLLECTION TYPE: URBAN (MOST RECENT OBLIQUE IMAGES)



URBAN - NORTH
IMAGE DATE: 17 July 2023




URBAN - SOUTH IMAGE DATE: 17 July 2023



COLLECTION TYPE: URBAN (MOST RECENT OBLIQUE IMAGES)



URBAN - EAST IMAGE DATE: 17 July 2023



URBAN - WEST IMAGE DATE: 17 July 2023




COLLECTION TYPE: WIDE AREA (MOST RECENT WIDE AREA ORTHO IMAGES)



WIDE AREA - NEIGHBORHOOD OVERVIEW

IMAGE DATE: 29 August 2023



WIDE AREA - ORTHO

IMAGE DATE: 29 August 2023